JBS Bay and Wall Cleaner ST-275

330 GALLON 440

RAW MATERIALS	AMOUNT (LBS.)	AMOUNT (LBS.)
Water	1334	1779
JBS Citric 48%	323	430
Glycol Ether EB	75	100
DDBSA	195	260
Hydrochloric Acid 31%	968	1291
Phosphoric Acid 75%	75	100
Superwet 91-6	58	77

DIRECTIONS

1 Fill tank with Water to the specified weight

2 Add JBS Citric acid solution, then EB while mixing

3 Add DDBSA relatively slowly and allow to mix for 15 minutes

4 Put of Breathing protection and add Hydrochloric Acid while mixing, allow to mix for 5 minutes

5 Add all other ingredients in order and mix for 20 minutes.